Machine Update

NSLS Town Meeting

Emil Zitvogel

Wednesday, August 15, 2012






Topics

- > Statistics
- May Shutdown Activities
- Fall Schedule
- Modified September Start Dates
- August/September Shutdown Tasks
- Transverse Beam Profile Monitor in VUV Ring
- VUV Injection Model
- > X-Ray Down-Ramp
- Closing Remarks






FY2012 Statistics Through July 31



Activity /Hours	UV/IR	X-ray
Operations	4717.9	4280.1
Unscheduled Operations	429.6	507.9
Maintenance	1438.4	1486.0
Other	734.1	1045.9

Other Activities	UV/IR	X-ray
Studies	2.3%	3.2%
Com/Con	2.1%	2.6%
Holiday	3.0%	3.0%
Injection	0.7%	1.1%
Unscheduled Downtime	1.5%	2.5%
Interlock	0.4%	2.0%

YTD 7320 Hrs 100 Hrs= 1.4%



User Metrics	UV/IR	X-ray
Reliability	97.8%	95.9%
Availability	106.7%	107.3%



May Shutdown Activities

- BUESH2 magnet lead repair
 - The copper lead failed prior to the shutdown
 - Since this failed several times, a new piece was made using Glidcop (more resistant to mechanical fatigue and failure)
- Trane Chillers were rebuilt and sealed using epoxy
- Preventative Maintenance for 3 of 4 electrical substations
- X17 cryo maintenance
 - Found broken lead in a heater in the purifier
 - May have caused insufficient purging of impurities
 - Operated well since this repair
 - Keeping to full warm-up (12 days) every other monthly maintenance





Fall Schedule

X-Ray										F	Y201	3										
Week		Aug	August			September					Octo	October			Nove	ember			D	ecemb	er	
Beginning	5	12	19	26	2	9	16	23	30	7	14	21	28	4	11	1/3	25	2	9	16	23	30
Sunday	0	0	М	М	М	М	М	С	0	0	0	0	0	0	0	0	М	М	М	М	М	М
Monday	O/S	O/M	М	М	Н	М	М	В	O/S	0	OIS	O/S	0	OIS	O/S	0	М	М	М	М	Н	М
Tuesday	S/T	М	М	М	M	М	М	0	S/T	0	S/O ¹	S/M	0	S/O ¹	S/T	0	М	М	М	М	Н	
Wednesday	0	М	М	М	М	М	М	0	0	0	0	M/C	0	0	0	O/M	М	М	М	М	М	1
Thursday	0	М	М	M	М	М	I/C	0	0	0	0	S/O ¹	0	0	q	Н	М	М	М	М	М	
Friday	0	М	М	М	M	М	С	0	0	0	0	0	0	0	4	Н	М	М	М	M/H	М	
Saturday	0	М	М	М	М	М	С	0	0	0	0	0	0	0	b	М	М	М	М	М	М	
												V										
VUV-IR										F	Y201	3			+							
Week		Aug	ust			Se	pteml	oer		October				November				December				
Beginning	5	12	19	26	2	9	16	23	30	7	14	21	28	4	11	18	25	2	9	16	23	30
Sunday	0	0	М	М	М	М	М	0	0	0	0	O/S ³	0	0	d	0	М	М	М	М	М	М
Monday	O/X	O/M	М	М	Н	М	M/C	0	O/X	O/X	0	S/M	O/X	0	O/X	0	М	М	М	М	Н	M
Tuesday	0	М	М	М	M	М	С	O/S ²	0	0	O/S ²	M/C	0	O/S ²	0	0	М	М	М	М	Н	
Wednesday	0	М	М	М	М	М	C/S	S	0	0	S	0	0	S	0	O/M	М	М	М	М	М	
Thursday	0	М	М	М	М	М	0	0	0	0	0	0	0	0	0	Н	М	М	М	М	М	
Friday	O/S ¹	М	М	М	М	М	0	0	O/S ¹	O/S ¹	0	O/X	O/S ¹	0	O/S ¹	H	М	М	М	M/H	М	
	0	М	М	М	М	М	0	0	0	0	0	0	0	0	0	М	М	М	М	М		

Full winter shutdown in the face of expected challenging budget allocation





Modified September Start Dates

- Since time was lost in July, we will start earlier than planned in September with unscheduled ops
- VUV start-up moved to afternoon of Weds 9/12
- VUV unscheduled ops beginning Fri 9/14 noon
- X-ray start-up moved to Thurs 9/13 evening following interlock checks
- X-ray unscheduled ops beginning no later than Mon 9/17 at 8 am
- Experimental water will be started on Sept 4th at 8 am





August/September Shutdown Tasks


- RF Preventative Maintenance
- Power Supply PM
- Main Magnet PM
- Poly-Flo Air and Water Line Change
- Proteus Maintenance
- Filter Maintenance
- BAC Cooling Tower Bearing Replacement & PM*
- Long List of Other Utilities PM
- Linac/Booster Quad Power Supply Replacement
- * Depends on the resolution of fixed ladder use





Transverse Beam Profile Monitor in VUV Ring

- A new Beam Profile Monitor was installed in the VUV ring.
- Driving force is that upon failure of current beam profile monitor, there would be no backup system for beam profile diagnostic.
- O.Ivashkevych, Y.Hidaka, and ZY (Z.Yin) developed, installed and tested a new EPICS-based imaging system using NSLS-II Control System Studio.
- Cost of the hardware \$1300








VUV Injection Model


- The interactive VUV injection model based on turn-by–turn diagnostics installed in the ring is a valuable diagnostic tool allowing detailed analysis of the ring injection settings.
- When the recent VUV injection problems began, our model, along with other diagnostics, helped us to pinpoint the source of the problem as booster extraction, and provided a convenient way to compare results of tuning.
 - injection recorded at nominal settings
 - problem injection (analysis has pointed to the Booster extraction as a most probable source of the troubles)
 - injection recorded after Booster extraction was tuned





S. Seletskiy

X-Ray Down-Ramp





Closing Remarks

The Photon Science staff continues carry out an effective preventative maintenance program that will take us to the start of NSLS-II

Our Accelerator Physics staff continues to look for ways to improve operations in the face of tight budgets

Thank you.



